INDEX OF STANDARD DETAILS

- 1. Blow out patch small holes
- 2. Blow out patch large holes
- 3. Flush patch small
- 4. Wall penetrations
- 5. Wall penetrations
- 6. Multiple wall penetrations
- 7. Junction box stud wall detail
- 8. Recessed wall cabinet
- 9. Smoke and rated partition adjacent to beam 6" or more
- 10. Two hour rated shaft walls
- 11. Rated partition under beam
- 12. Smoke and rated partition adjacent to beam 4" to 6"
- 13. Smoke and rated partition adjacent to beam 2" to 4"
- 14. Rated partition under beam and joist
- 15. Rated wall perpendicular to beam
- 16. Bar joist wall penetration blow out patch
- 17. Bar joist wall penetration flush patch
- 18. Rated wall parallel to deck sprayed
- 19. Rated wall parallel to deck unsprayed
- 20. Priority wall legend
- 21. Fire / smoke wall plan view detail
- 22. Horizontal joint requirements above suspended ceilings
- 23. Joint requirements 2 hour wall
- 24. Smoke resistant and hazardous function separation walls
- 25. Wall penetration rated ceiling assembly
- 26. Wall penetration rated ceiling assembly
- 27. Wall section smoke and one hour
- 28. Wall section smoke and one hour
- 29. Wall section rated block
- 30. Wall section 2 hour plaster shaft wall
- 31. Access panel installation
- 32. Bulkhead at assembly transition
- 33. Damper sleeve installation
- 34. Rated ceiling penetration
- 35. Membrane edge support
- 36. Temporary 1 hour partition between construction and occupied areas

INTRODUCTION

In late 1982, a south Florida hospital failed the State's final inspection. The obvious cause was the drywall installation. The "HRS" survey team was Joe Alcure, George Hapsis, Bob Smyre, Dr. Ludwig and Richard Rosenvold. A chalkboard was brought into the building under construction. Alcure identified that the biggest problems were: 1. Holes in the rated walls; and 2. Insufficient screws to attach the drywall boards to the steel framing.

The solution to Number 2 was obvious. More screws were added to the drywall and to the steel framing as required by the wall rating.

The solution to the Number 1 was to cut a piece of scrap drywall material larger than the hole to be repaired, mud this patch and, after applying it over the hole, to add "lamating" drywall screws at 6" on center around the edge of the this patch.

The patch further developed as we learned that screws should be inset at least 3 inches to control a tendency to tear out of a non-hardened edge of drywall.

It was further found that when a larger patch was required, it should be supported by screwing it into the steel framing. We see this indication on Detail 2.

Where pipe or conduits were penetrating the rated partition, the patch was cut in half and tightly fitted around the pipe or conduit. Detail 3 is accepted as a means to provide a flush finished wall especially below finished ceilings.

As particular construction problems are presented to the field staff, much time and consideration is given to finding solutions. When the Office of Plans and Construction, and national consultants are in general agreement, a new "detail" is produced and then distributed.


These AHCA Standard Details will be acceptable to the Office of Plans and Construction as a solution to a repair or a construction problem when used as described.

These details are untested by any independent testing laboratory and in no way imply that they exceed local jurisdictional rights.

Although some of these details such as the "blow out" patch have been tested by some drywall manufacturers, these details will generally not be found in any tested assemblies. Therefore, local jurisdictions may enforce more stringent requirements.




SMALL OPENINGS MAY BE PATCHED USING JOINT COMPOUND, CAULK, OR BLOW-OUT PATCHES.



LARGE OPENINGS REQUIRE A BLOW-OUT PATCH OR WALL REPAIR.

SMOKE RESISTANT WALLS



UP TO 1/2" OPENINGS MAY BE FILLED FULL DEPTH OF DRYWALL WITH ACOUSTICAL SEALANT. STRIKE OFF AT FACE OF DRYWALL. DO NOT SPREAD BEYOND OPENING. ALTERNATIVELY, A PROPRIETARY SYSTEM MAY BE USED.

UP TO 1/4" OPENINGS MAY BE FILLED WITH JOINT COMPOUND.


UP TO 1/8" OPENINGS DO NOT REQUIRE ANY TREATMENT.


LARGER THAN 1/2" OPENINGS REQUIRE A BLOW-OUT PATCH (SEE DETAIL SHEET 2). SOME LOCAL JURISDICTIONS DO NOT ALLOW THE BLOW-OUT PATCH.

30-MIN., 1-HR. & 2-HR. RATED WALLS (FIRE, FIRE & SMOKE) 3- AND 4-HR. WALLS REQUIRE THE USE OF A PROPRIETARY SYSTEM

A.H.C.A. STANDARD DETAIL NO.	٥.	NO	DETAIL	NDARD	STA	H.C.A.	A.
------------------------------	----	----	--------	-------	-----	--------	----

Issued:	Oct.	12,	1993
Revised:			
10198	9 90		17,0





HOLES UP TO 3" DIA.

TYP. SECT.

HOLES UP TO 3" DIA.

BLOW-OUT PATCH


ONLY 1 LAYER ON EACH SIDE OF WALL REQUIRED FOR 1 OR 2 HOUR WALLS. BLOW-OUT PATCH IS NOT ACCEPTABLE ON WALLS RATED AT 3 OR 4 HOURS.

NOTES:


- 1. BUTTER ENTIRE BACK SIDE OF PATCH WITH JOINT COMPOUND.
- 2. LEAVE ALL SCREWS EXPOSED.

A.H.C.A. STANDARD DETAIL NO. 2


Issued:	Oct.	12,	1993
Revised:			A
OHA ZHAJ9	70		10



PARTIAL ELEVATION




PARTIAL ELEVATION




FLUSH PATCH - SMALL

A.H.C.A. STANDARD DETAIL NO. 3

ssued:	OCI.	12,	1993
Revised:			
	AOR Y	079	DA.





FIRE OR SMOKE WALL PENETRATIONS

PLASTER, DRYWALL, CONCRETE, OR MASONRY

TYPICAL SEAL AS FOLLOWS:


LESS THAN 1/2" = ACOUSTIC CAULK OR DRYWALL

JOINT COMPOUND (NO TAPE)


MORE THAN 1/2" = BLOW-OUT PATCH OR PROPRIETARY SYSTEM.

A.H.C.A. STANDARD DETAIL NO. 4

Issued:	Oct. 12, 1993
Revised:	LO.H.A
	FOR BORROE OF
	NY TUNGLA




CONCRETE MASONRY UNITS OR SOLID CONCRETE WALLS




GYPSUM PLASTER, METAL LATH AND METAL STUD PARTITIONS

A.H.C.A. STANDARD DETAIL NO. 5

Issued:	Oct.	12,	1993
Revised:	30	TOP	10
	UT I	W.J.	JA






SECTION A-A

ALTERNATE 1 OR 2 MAY BE USED ON EITHER SIDE OF WALL. ONE SIDE OF PENETRATION MAY REMAIN OPEN.

A.H.C.A. STANDARD DETAIL NO. 6

Oct.	12,	1993	
10 3	0(4)		
	Oct.	Oct. 12,	Oct. 12, 1993



SHALLOW FIVE SIDE BOX DETAIL

REQUIRED WHERE BOX EXCEEDS 16 SQ. INCHES OR AGGREGATE OF BOXES EXCEEDS 100 SQ. IN./

ELECTRICAL JUNCTION BOXES

WHEN A METALLIC JUNCTION BOX FOR ELECTRICAL RECEPTACLES OR SWITCHES IS CONTAINED WITHIN A RATED WALL OF GYPSUM DRYWALL CONSTRUCTION AND AN OPENING IS PROVIDED FOR THE BOX IN THE SURFACE OF THAT WALL, THE AREA OF THE OPENING MAY NOT EXCEED 16 SQUARE INCHES, UNLESS THE JUNCTION BOX IS ENCLOSED BY A "5-SIDED BOX" (SEE APPROVED DETAILS).


THE AGGREGATE AREA OF ALL SUCH JUNCTION BOXES IN A RATED WALL NOT ENCLOSED BY "5-SIDED BOXES" DESCRIBED ABOVE SHALL NOT EXCEED 100 SQUARE INCHES IN 100 SQUARE FEET OF WALL AREA AS MEASURED FROM FLOOR TO STRUCTURAL DECK OR RATED MEMBRANE.

JUNCTION BOXES WITH OPENINGS ON OPPOSITE FACES OF RATED WALLS SHALL HAVE A HORIZONTAL SEPARATION OF 24 INCHES AS A MINIMUM, REGARDLESS OF BOX SIZE, UNLESS ENCLOSED BY "5-SIDED BOXES."

LOCATIONS OF STUDS DO NOT HAVE ANY BEARING ON THE ABOVE REQUIREMENTS, NOR DOES THE USE OF MINERAL WOOL FIRE SAFING ALTER THESE REQUIREMENTS.

A.H.C.A. STANDARD DETAIL NO. 7

Issued:	Oct. 12, 1993
Revised:	H RO BORRE ACENICA ECO
	STATE OF FU




RECESSED WALL CABINET

WALL OF CYPSUM DRYWALL COMSTRUCTION AND AN OPENING IS PROVIDED FOR THE SOX IN THE SURFACE OF


A.H.C.A. STANDARD DETAIL NO. 8

HOLD THELL	PRODUCE PARTITIONS	
Issued:	Oct. 12, 1993	
Revised:	AGUA	
OVA SVAJ	10 30110	



SMOKE & RATED PARTITION ADJACENT TO BEAM

A.H.C.A. STANDARD DETAIL NO. 9




TWO — HOUR RATED SHAFT WALLS SPRAY FIREPROOFING MUST HAVE 2—HOUR THICKNESS OR GREATER.

A.H.C.A. STANDARD DETAIL NO. 10

Issued:	Oct.	12,	1993	
Revised:		l A		
	Ser 1968 St. 18	5 200		
	TO S E		1	•




SECTION - VERTICAL JT. AT BEAM



DETAIL - RATED PARTITION UNDER BEAM

A.H.C.A. STANDARD DETAIL NO. 11


200	Issued:	Oct.	12,	1993	
	Revised:	9 30	301	110	



SMOKE & RATED PARTITION ADJACENT TO BEAM N.T.S.

A.H.C.A. STANDARD DETAIL NO. 12

Issued:	Oct. 12, 1993
A TOTAL	000. 12, 1000
Revised:	Market a The Mark
PLANS AND	OFFICE OF
HTJA3H J	TOT TUPLOUR




SMOKE & RATED PARTITION ADJACENT TO BEAM (STRUCTURALLY BOXED IN)

N.T.S.

A.H.C.A. STANDARD DETAIL NO. 13

Issued:	Oct.	12,	1993
Revised:	P A	Y JA. Yili	777W 470A




RATED PARTITION UNDER BEAM N.T.S.

RATED PARTITION UNDER JOIST N.T.S.

A.H.C.A. STANDARD DETAIL NO. 14

Issued:	Oct.	12,	1993
Revised:	AC		L.A.
	<u> </u>	77.45	ma.




<u>DETAIL -- RATED WALL PERPENDICULAR TO BEAM N.T.S.</u>

A.H.C.A. STANDARD DETAIL NO. 15

OFFICE OF PLANS AND CONSTRUCTION AGENCY FOR HEALTH CARE ADMINISTRATION STATE OF FLORIDA


Issued: Oct. 12, 1993
Revised:



BLOW OUT PATCH BAR JOIST PENETRATION OF A RATED WALL N.T.S.

A.H.C.A. STANDARD D	ILIAIL N	U.	0
---------------------	----------	----	---

Issued:	Oct.	12,	1993
Revised:		4 /	
PLANS AM	an 3	100	




FLUSH WALL CONSTRUCTION BAR JOIST PENETRATION OF A RATED WALL N.T.S.

A.H.C.A. STANDARD DETAIL NO. 17

OFFICE OF PLANS AND CONSTRUCTION AGENCY FOR HEALTH CARE ADMINISTRATION STATE OF FLORIDA

Issued: Oct. 12, 1993


Revised: MAY 5, 1994



FLUSH WALL CONSTRUCTION BAR JOIST PENETRATION OF A RATED WALL N.T.S.

Issued: Cot 12, 1993. Revised task 5, 1994

ALHLOLAL STANDARD DETAIL NO. 17



TYPICAL RATED WALL PARALLEL TO DECK N.T.S.

Δ	H	$C \Delta$	STANI	DARD	DETAIL	NO	18
₽1.	.П.	U.A.	SIMIN	DAND	DLIAL	IVO.	10


Issued:	Oct.	12,	1993
Revised:			



TYPICAL RATED WALL PARALLEL TO DECK

O. 18


DEFICE OF PLANS AND CONSTRUCTION
CENTLY FOR HEALTH CARE ADMINISTRATION



TYPICAL RATED WALL PARALLEL TO DECK
N.T.S.

A.H.C.A. STANDARD DETAIL NO. 19

Issued:	Oct.	12,	1993
Revised:	1 - 107 1803 - 1		1941 194
	9 30	377	172



WALL PRIORITY LEGEND


TWO	HOUR FI	IRE & SMOKE WALL -	PRIORITY	1	HIGHEST
TWO	HOUR FI	IRE WALL	PRIORITY	2	
TWO	HOUR S	HAFTWALL ——	1 111011111	_	
ONE	HOUR F	IRE & SMOKE WALL	PRIORITY	3	
ONE	HOUR F	IRE WALL -	PRIORITY	4	
NON-	-RATED \	WALL ————	PRIORITY	5	LOWEST

NOTES:

- 1. SCHEDULE CONSTRUCTION OF WALLS ACCORDING TO PRIORITY.
- 2. ALL PRIORITY 1 THRU 4 WALLS SHOULD BE FRAMED WITH ONE SIDE DRYWALLED AT THE 40% CONSTRUCTION SURVEY.
- 3. BOTH SIDES OF PRIORITY 1 THRU 4 WALLS SHALL BE SEALED AND STENCILLED AT THE 80% CONSTRUCTION SURVEY.

A.H.C.A. STANDARD DETAIL NO. 2	AHCA	STANDARD	DETAIL	NO.	20
--------------------------------	------	----------	--------	-----	----


				_
Issued:	Oct.	12,	1993	
Revised:			A	
	142 100 8	1 1 10	91	
				•



PLAN VIEW - FIRE AND/OR SMOKE WALL AT EXTERIOR WALL

Δ	HCA	STAND	ARD	DETAIL	NO	21
$\boldsymbol{\Lambda}$		SIMIL		DEIAL	IVO.	

ssued:	Oct.	12,	1993
Revised:			70
			rate in the




HORIZONTAL JOINT REQUIREMENTS ABOVE SUSPENDED CEILINGS

NOTES:

- 1. JOINTS MAY BE OPPOSITE IF SAFEING IS USED IN CAVITY. REF: CEG 8-11-83 CEG 5-9-84
- 2. JOINTS IN FINISH LAYER TO RECEIVE TAPE AND JOINT COMPOUND

A.H.C.A. STANDARD DETAIL NO. 22

Issued:	Oct.	12,	1993	
Revised:			Ą	
ELANS ANE	an :	MIT.	10	



PLAN VIEW - TYPICAL JOINT REQUIREMENTS 2 HOUR WALL


NOTES:

- 1. GYPSUM BOARD APPLIED VERTICALLY
- 2. JOINTS IN FINISH LAYER TO RECEIVE TAPE AND JOINT COMPOUND

A.H.C.A. STANDARD DETAIL NO. 23

OFFICE OF PLANS AND CONSTRUCTION AGENCY FOR HEALTH CARE ADMINISTRATION STATE OF FLORIDA

Issued: Oct. 12, 1993
Revised:





SECTION

SMOKE RESISTANT WALLS AND HAZARDOUS FUNCTION SEPARATION WALLS AS DEFINED IN STANDARD BUILDING CODE 409.1.5.

A.H.C.A. STANDARD DETAIL NO. 24

Issued:	Oct.	12,	1993
Revised:			Á
			90
HIJAJH	107	MCN	OA.






RATED PARTITION PENETRATION OF 1-HR RATED CEILING ASSEMBLY

A.H.C.A. STANDARD DETAIL NO. 25


Issued:	Oct.	12,	1993
Revised:	9 70	30	790 44.0



PARTITION PENETRATION OF 1 HR. RATED MEMBRANE N.T.S.

A.H.C.A. STANDARD DETAIL NO. 26

Issued:	Oct. 12, 1993	_
Revised:	A.O.H.A	
	9 76 30170	
	ACENCY FOR	




SECTION — SMOKE & ONE—HOUR PARTITION (PERPENDICULAR TO DECK) N.T.S.

TEST REF: T-3362-OSU T-1174-OSU GA-WP-1200

A.H.C.A. STANDARD DETAIL NO. 27

Issued:	Oct.	12,	1993
Revised:	70 3	017	0




<u>SECTION - SMOKE & ONE-HOUR PARTITION</u> (PERPENDICULAR TO DECK) N.T.S.

TEST REF: T-3362-OSU T-1174-OSU GA-WP-1200

A.H.C.A. STANDARD DETAIL NO. 28


Issued:	Oct.	12,	1993
Revised:	0.1	4 /	



WALL SECTION — TYP. RATED BLOCK WALL FIRE OR SMOKE
N.T.S.

A.H.C.A. STANDARD DETAIL NO. 29


	Issued:	Oct.	12,	1993	
Re	Revised:	4 40	200	190	
		16.30	31		




2 HOUR PLASTER SHAFTWALL MAXIMUM HEIGHT 18'-0"

A.H.C.A. STANDARD DETAIL NO. 30

Revised:	A
OF PLAYS AND	990







ACCESS PANEL INSTALLATION N.T.S.

A.H.C.A. STANDARD DETAIL NO. 31

Issued:	Oct.	12,	1993
Revised:	19. 1	7	MERC



CHANGE OF CEILING HEIGHT AT RATED CEILING





BULKHEAD AT 1 HR. RATED CEILING ASS'Y.

NOTE: 2 LAYERS 5/8" TYPE "X" DRYWALL AT 2 HOUR RATED CEILING ASSEMBLY

A.H.C.A. STANDARD DETAIL NO. 32

Issued:	Oct.	12,	1993	p began
Revised:	A) [A	
O GVA SNA		10	660.	






DAMPER SLEEVE INSTALLATION


NOTE:
SPECIFIC FRAMING REQUIREMENTS OF OPENINGS
SHOULD BE PROVIDED IN THE ARCHITECTURAL
AND STRUCTURAL DRAWINGS THAT ARE SUBMITTED
FOR BUILDING PERMITS.


A.H.C.A. STANDARD DETAIL NO. 33

Issued:	Oct.	12,	1993	
Revised:	30.3	019	0	
	U 1 Y.	AN A)A 	



SECTION 1-1







PENETRATION IN RATED CEILING
N.T.S.

A.H.C.A. STANDARD DETAIL NO. 34

Issued:	Oct	12	1993
155060.	oct.	12,	1333
Revised:			
	legica i seci		
	17 16	11,1%	A.






A.H.C.A. STANDARD DETAIL NO. 35

Issued:	Oct.	12,	1993
Revised:			






MEMBERNE EDGE SUPPORT NOTE ELOCICIO IN WALL IS REQUIRED

		MDARD	

FFREE OF PLANS AND CONSTRUCTION
CORRECTOR FOR HEALTH CARE ADMINISTRATION
LIATE OF BIORINA



9 8 Archite
1221 Ha
1 U Winnea

Hammel Green & Abrahamson Inc.
Architects & Engineers
1201 Harmon Place
Wicheapolis, Hinnesons 55470

3/4" = 1-01 DATE

